

PC2 basic practices

YOU MUST COMPLY WITH ALL THE GENE TECHNOLOGY REGULATORS'S REQUIREMENTS FOR THIS FACILITY EVEN IF YOUR WORK DOES NOT INVOLVE GENTICALLY MODIFIED ORGANISMS (GMOs)

- Wear required protective clothing (lab coat) & enclosed shoes
- Decontaminate work benches, surfaces & equipment after any spills & when laboratory work is completed.
- Ensure all waste is decontaminated by the appropriate method.
- Decontaminate all work surfaces & equipment where maintenance is to be carried out.
- Do not bring food or drink into the facility.
- Remove protective clothing & decontaminate your hands before leaving the facility.
- Report all unintentional releases of GMOs to the OGTR as soon as practicable.
- Transport GMOs in accordance with the *Regulator's Guidelines for the Transport of GMOs* (June 2001).

YOUR RESPONSIBILITIES ARE DETAILED IN THE CERTIFICATION INSTRUMENT FOR THIS FACILITY & OGTR GUIDELINES FOR PC2 FACILITIES